

21007 HEAD MODIFICATION

THE CYLINDER HEAD MUST BE MODIFIED AS SHOWN ON THE DRAWING THAT IS INCLUDED.
FAILURE TO MODIFY THE HEAD WILL RESULT IN ENGINE DAMAGE.

